


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

BEREAH QUADRANGLE
FLORIDA
7.5 MINUTE SERIES (TOPOGRAPHIC)



Produced by the United States Geological Survey
Control by USGS and NOS/NOAA
Culture and drainage in part compiled from aerial photographs taken 1952. Topography by planetable surveys 1956
Projection and 10,000-foot grid ticks: Florida coordinate system, west zone (transverse Mercator)
1000-meter Universal Transverse Mercator grid ticks, zone 17, shown in blue
1927 North American Datum (NAD 27)
North American Datum of 1983 (NAD 83) is shown by dashed corner ticks
The values of the shift between NAD 27 and NAD 83 for 7.5-minute intersections are given in USGS Bulletin 1875
Photinspected from 1990 source; no major culture or drainage changes observed. Boundaries and names verified 1993
Dashed contours in strip mine areas represent conditions before being mined
Light purple tint indicates reclaimed strip mine areas

UTM GRID AND 1993 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET
3° 15' 00" W
01° 18' 00" W
62 MILS
8 MILS
Revisions shown in purple and woodland compiled in cooperation with State of Florida agencies from aerial photographs taken 1984 and other sources. This information not field checked
Map edited 1987

SCALE 1:24,000
1 1000 0 1000 2000 3000 4000 5000 6000 7000 FEET
1 5 0 1 KILOMETER
CONTOUR INTERVAL 5 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929
THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U. S. GEOLOGICAL SURVEY
DENVER, COLORADO 80225 OR RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

QUADRANGLE LOCATION
FLORIDA
ADJOINING 7.5' QUADRANGLE NAMES
1 2 3
4 5
6 7 8
1 Homeland
2 Alturas
3 Babson Park
4 Bowling Green
5 Frostproof
6 Wauchula
7 Griffins Corner
8 Avon Park

ROAD CLASSIFICATION
Primary highway, hard surface
Secondary highway, hard surface
Light-duty road, hard or improved surface
Unimproved road
Interstate Route
U. S. Route
State Route
BEREAH, FLA.
27081-F6-TF-024
1956
PHOTOREVISED 1987
MINOR REVISION 1993