


597 IV NW
(MCKENZIE NW)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


STATE OF NORTH DAKOTA
WATER COMMISSION

STERLING QUADRANGLE
NORTH DAKOTA—BURLEIGH CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
SE 1/4 MCKENZIE 15' QUADRANGLE

597 IV NW
(CLEAR LAKE)



Maped, edited, and published by the Geological Survey
in cooperation with the North Dakota Water Commission
Control by USGS and NOS/NOAA
Topography by photogrammetric methods from aerial
photographs taken 1974. Field checked 1975
Projection and 10,000-foot grid ticks: North Dakota coordinate
system, south zone (Lambert conformal conic)
1000-meter Universal Transverse Mercator grid,
zone 14. 1927 North American datum
Fine red dashed lines indicate selected fence and field lines
where generally visible on aerial photographs
This information is unchecked



ROAD CLASSIFICATION
Primary highway, light-duty road, hard or improved surface
Secondary highway, hard surface
Unimproved road
Interstate Route
U. S. Route
State Route

STERLING, N. DAK.
SE 1/4 MCKENZIE 15' QUADRANGLE
N4645-W10015/7.5
1975
AMS 5977 IV SE—SERIES V871

2800
JAN 30 1978